

# GENERAL DESCRIPTION OF MT-1

## Technical Parameters

- Measuring temperature in two places simultaneously
- Measuring Range:  $-50^{\circ}\text{C}\sim+70^{\circ}\text{C}$
- Error Margin:  $\pm 1^{\circ}\text{C}$
- Resolving Power:  $0.1^{\circ}\text{C}$
- Switch between Centigrade and Fahrenheit
- Clock function
- 12/24-hour mode display
- Power Supply: 1.5V

## Operational Instructions

- When turned on, the LCD screen will display the degree of the temperature and the time in 6 seconds after measuring it.
- Shortly press key[Set], you can change 12/24-time mode and a bit longer than 3 seconds, you can set your time with the figure displaying H flashing.
- Then press[Up]key for hour change and if the key pressed more than 2 seconds, the figure will be rapidly adjusted at the rate of 4 HZ.
- Press Key[Set], now you can set the figure in S place; refer to the above for its adjustment.
- Shift between Centigrade and Fahrenheit available.