

# Instruction of MT-3

## Features:

- Measure indoor/outdoor temperature and indoor humidity at the same time
- Automatically memorize max/min value of indoor/outdoor temperature and indoor humidity
- Indoor comfort degree displaying
- Switch between °C and °F
- Battery voltage volume automatically detect

## Technical parameters:

- Indoor temperature measuring range: -30°C ~ +50°C (-22°F ~ 122°F)
- Outdoor temperature measuring range: -50°C ~ +70°C (-58°F ~ 158°F)
- Indoor humidity measuring range: 20% ~ 99% (Relative humidity)

## Operation instruction:

- Automatically memorize **Max/Min** value of indoor/outdoor temperature and indoor humidity
- Press **MAX** key to display memorized indoor/outdoor max temperature and indoor max humidity
- Press **MIN** key to display memorized indoor/outdoor min temperature and indoor min humidity
- Press **RESET** to clear memorized value and start to memorize new max/min value
- Switch °C/°F to display Celsius or Fahrenheit
- Display "LOWBAT" when the battery voltage is low
- Indicate the comfort degree as below:

